



# 2018 Mitsubishi Vehicle Diagnostic Report

## Vehicle Information

2018 / Mitsubishi / OUTLANDER (GF#) /  
VIN: JE4LZ21W3JZ701717

Odometer Reading: 208480km  
License Plate: 31358/Y



Scan to download  
PDF

## Customer Information

Name: ministry

















## Device information

Scanner: MaxiSys MS909  
Version: V3.00

Serial Number: V19GN5C01153

Repair Order Number: V19GN5C0115320240430083340575

## System Scanned ( 15 )

System	Status/DTC
MPI/GDI/Diesel	 1
AT/CVT/A-MT/TC-SST	 0
ABS/ASC/ASTC/WSS	 0
SRS-Air Bag	 0
Meter	 0
TPMS - without KOS	 3
Air Conditioner	 0
Auto Cruise	  0
4WS/Electric Power Steering	 0
ETACS	 3
KOS/IMMO/Keyless - IMMOBI & Keyless	 3
Steering Angle Sensor	 0
AUDIO - CD AUDIO	 0
Corner Sensor/Sonar	 0
AWC	 0

## DTC (10)

MPI/GDI/Diesel ( 1 DTC )

DTC	Description	Status
P0421	Warm up catalyst deterioration 1	Stored DTC

TPMS - without KOS ( 3 DTCs )

DTC	Description	Status
C1912	Tyre air pressure low, Tyre1	Stored DTC
C1931	Tyre ID reception fail, Tyre3	Active DTC
C1932	Tyre air pressure low, Tyre3	Stored DTC

ETACS ( 3 DTCs )

DTC	Description	Status
C1912	Tyre air pressure low, Tyre1	Stored DTC
C1931	Tyre ID reception fail, Tyre3	Active DTC
C1932	Tyre air pressure low, Tyre3	Stored DTC

KOS/IMMO/Keyless - IMMOBI & Keyless ( 3 DTCs )

DTC	Description	Status
C1912	Tyre air pressure low, Tyre1	Stored DTC
C1931	Tyre ID reception fail, Tyre3	Active DTC
C1932	Tyre air pressure low, Tyre3	Stored DTC

Technician Notes

Customer Name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note: Please save a copy of this report for your records.